

1/7




FIG. 1




FIG. 2

2/7




FIG. 3




FIG. 4

3/7




FIG. 5




FIG. 6

4/7




FIG. 7

5/7

Stress(Strain) curve- Al-alloys -2 μ m
strain rate: 1e-6 - sputtered by GvL




FIG. 8

6/7





FIG. 9

7/7




FIG. 10




FIG. 11